


Product Change Notice

August 30, 2010

HP 10A Power Relays: Change in anchor screw colors



1. Affected Products:

HP relays with contact arrangement 2 Form C and 4 Form C. (Note: excludes 3 Form C.)
 Part numbers: **HP2** _ _ _ _ , **HP4** _ _ _ _

2. Description: Change in color of the anchor screw from red to black.

	Before change (bottom)	After change (bottom)
HP relay 2 Form C		
Color of anchor screw	Red	Black
HP relay 4 Form C		
Color of anchor screw	Red	Black

3. Reason: Improved color retention.

4. Part Numbers and performance remain unchanged.

5. Product Identification:

Change will be distinguished by the letter “TH” at the end of the manufacturing lot number.

5. Schedule: Effective June 2010 (production basis).

Any questions, please contact your local Panasonic Electric Works Sales representatives.

Ref#: T-1207