

Correction Notice


November 15, 2010

Not Recommended for New Design Notice (September 2010) for JC Relay Plug-in Type: Addendum (Correction)


Description:

The Not Recommended for New Design (NRFND) notice issued on September 2010 for **JC relay plug-in type** (ref# NRFND-T-1215) included **1 Form A** relays only. It should also include **2 Form A** version.

RELAYS (INCORRECT)

Product Name	Type	Old P/N	Substituted Product Name	Substituted P/N
JC Relays 	Plug-in	JC1aF-S-	JC relay PC Board Type	JC1aF-DC(XX)V-F

RELAYS (CORRECT)

Product Name	Type	Old P/N	Substituted Product Name	Substituted P/N
JC Relays 	Plug-in	JC1aF-S- JC2aF-S-	JC relay PC Board Type	JC1aF-DC(XX)V-F JC2aF-DC(XX)V-F

Please contact Panasonic Electric Works representatives with any question.

(Ref# T-1225_NRFND-T-1215)