

Product Discontinuation Notice


February 2012

Discontinuation of ADP4 and ADP1 Pressure Sensors



1. Reason: Low market demand

2. Affected parts:

<p>PS (ADP4) and PF (ADP1) pressure sensors</p> 	<p>14.7 kPa types</p>	<p>ADP41110 ADP42110 ADP1111 ADP1211</p>
---	---------------------------	--

3. Last time buy: End of August 2012

4. Substitution:

<p>PS (ADP4) and PF (ADP1) pressure sensors 34.3 kPa type</p>	<p>ADP41210 ADP42210 ADP1121 ADP1221</p>
---	--

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-14)