

Product Discontinuation Notice


February 2012

Discontinuation of LJ Relays



1. Reason: Replacement part

2. Affected parts:

LJ (ALJ) relays 	All types	ALJO
---	-----------	------

3. Last time buy: End of August 2012

4. Substitution:

LD-P (ALDP) relays (The terminal pitch is different.)	ALDPO
---	-------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-06)