

## Product Discontinuation Notice

February 2012

### Discontinuation of Rocker Switches

---




---

**1. Reason: Low market demand**

---

**2. Affected parts:**

Rocker switches 	All types	WD3000
--	-----------	--------

---

**3. Last time buy: End of August 2012**

---

**4. Substitution: None**

---

Any questions, please contact your local Panasonic Electric Works Sales representatives.

---

(Ref#: T-1246-19)