

Product Discontinuation Notice


March 2012

Discontinuation of RP Relays



1. Reason: Low market demand

2. Affected parts:

RP relays 	All types	RP1-
---	-----------	------

3. Last time buy: End of August 2012

4. Substitution:

RS (ARS) relays (The terminal pitch and profile are different.)	ARS ○
---	--------------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-31)